

Addendum to Agenda Item 6 of the Meeting of the River Hamble Harbour Board on Friday 15 November 2019

- 5.100. 16 Oct. Patrol conducted mooring and pontoon checks. Pumped out two inundated tenders at Warsash. Planned patrol boat maintenance. Recovered two logs from the Main Channel.
- 5.101. 17 Oct. Patrol conducted mooring and pontoon checks. Planned patrol boat maintenance.
- 5.102. 18 Oct. Patrol conducted mooring and pontoon checks. Planned patrol boat maintenance.
- 5.103. 19 Oct. Patrol conducted mooring and pontoon checks. Tide gauge replacement. Planned patrol boat maintenance.
- 5.104. 20 Oct. Patrol conducted mooring and pontoon checks. Liaison with mooring holders regarding recent spate of thefts. Planned patrol boat maintenance. Responded to a call from a member of the public reporting a speeding RIB in the Upper Hamble. Gave assistance to a motor boat which had run out of fuel.
- 5.105. 21 Oct. Patrol conducted mooring and pontoon checks. Observation and reporting of bait digging on Lincegrove and Hackett's Marshes and North of the Grace Dieu wreck site (outside 150 yds). Checked a mid-stream moored yacht, apparently low in the water aft. No evidence of water ingress and vessel stable. Owner contacted. Planned patrol boat maintenance. Responded to a call from a member of the public reporting a person in the water on the 'G' Run. Patrol made best speed to the area and made contact with a male sitting in the cockpit of his mid-stream moored yacht. The male reported that he had fallen from his tender while conducting mooring maintenance. He was well but chilly. Having changed into dry clothing, he was given a thermal blanket and recovered to the harbour office for a warm drink. He declined further treatment after which patrol returned him and his tender to his sailing club.
- 5.106. 22 Oct. Patrol conducted mooring and pontoon checks. Planned patrol boat maintenance. Tide gauge replacement work. Routine boatyard liaison.
- 5.107. 23 Oct. Patrol conducted mooring and pontoon checks. Routine jetty maintenance River Hamble Country Park. Fitted a temporary pile-line on a mid-stream moored yacht. Owner informed. Liaison with Historic England regarding replacement of Grace Dieu marker buoy.
- 5.108. 24 Oct. Patrol conducted mooring and pontoon checks. First Aid checks. Check of works at RHCP jetty.
- 5.109. 25 Oct. Patrol conducted mooring and pontoon checks. Planned patrol boat maintenance. Recovered two pieces of timber from the Main Channel at the Rail Bridge.

- 5.110. 26 Oct. Patrol conducted mooring and pontoon checks. Recovered a tender belonging to a mid-stream moored yacht from Crableck. Liaison with owner. Halloween preparation. Pumped out an inundated tender at Warsash.
- 5.111. 27 Oct. Patrol conducted mooring and pontoon checks. Supported bird survey. Liaison with tender owner (5.110). Attended a mid-stream moored yacht which had reported a berthing collision. Another vessel had mis-judged his approach at the fuelling berth causing superficial damage. Skipper error. Details exchanged.
- 5.112. 28 Oct. Patrol conducted mooring and pontoon checks. Recovered and disposed of a dead deer from the River near the Bark Store. Routine boatyard liaison. Tide gauge fitting work. Patrol gave assistance to two dinghies returning to their club against a strong ebb.
- 5.113. 29 Oct. Patrol conducted mooring and pontoon checks. Routine liaison with the Pink Ferry. Assisted a yacht with propulsion failure to her berth.
- 5.114. 30 Oct. Patrol conducted mooring and pontoon checks. Liaison with and support to 'Wetwheels' Halloween event.
- 5.115. 31 Oct. Patrol conducted mooring and pontoon checks. Liaison with and support to 'Wetwheels' Halloween event. Planned patrol boat maintenance. Took a report from a marina regarding a berthing collision causing stanchion damage. Approaching yacht skipper mis-judged his approach to his berth. Details exchanged.
- 5.116. 01 Nov. Patrol conducted mooring and pontoon checks. Routine marina liaison. Recovered 'Wetwheels' Halloween decorations. Planned patrol boat maintenance.
- 5.117. 02 Nov. Patrol conducted mooring and pontoon checks. Responded to a report from a member of the public of a parted mooring line on a mid-stream moored yacht. Re-secured and other lines checked. Owner informed. Responded to call from a sailing club reporting a yacht aground on a rising tide at Warsash. Yacht mooring lines had parted in strong (40kt) winds. Patrol attended and pulled the yacht into deeper water before placing the yacht on the mid-stream VP. Owner informed through the Club. Patrol transferred a crew member of a visiting yacht ashore. Crew member had sustained a deep cut to his finger. Immediate first aid given and taxi ordered for transport to hospital for examination.
- 5.118. 03 Nov. Patrol conducted mooring and pontoon checks. Post maintenance checks on patrol craft.
- 5.119. 04 Nov. Patrol conducted mooring and pontoon checks. Replaced Grace Dieu protected wreck buoy. Routine jetty maintenance.
- 5.120. 05 Nov. Patrol conducted mooring and pontoon checks. Supported scaffolding work at HM Office.

- 5.121. 06 Nov. Patrol conducted mooring and pontoon checks. Patrol attended a small (1m²) spillage of hydraulic oil at Warsash. Source clear and admitted by owner. Deployed absorbent pads at cost to clear up. Boat coding work. Routine liaison with Hamble Lifeboat.
- 5.122. 07 Nov. Patrol conducted mooring and pontoon checks. Boat coding work. First Aid equipment checks. Routine pontoon maintenance work.
- 5.123. 08 Nov. Patrol conducted mooring and pontoon checks. Responded to a call from a marina of a small diesel oil spillage. Source not apparent. Broken up with propellor wash.
- 5.124. 09 Nov. Patrol conducted mooring and pontoon checks. Patrol stopped a small motor boat, speeding in the Upper River. Skipper warned for speeding and required to attend the Harbour Office to receive a written warning. Routine liaison with UK Border Force.
- 5.125. 10 Nov. Patrol conducted mooring and pontoon checks.
- 5.126. 11 Nov. Patrol conducted mooring and pontoon checks. Routine liaison with a River boatyard. Pump out at Warsash of inundated tenders.
- 5.127. 12 Nov. Patrol conducted mooring and pontoon checks.