

Agenda Item 6

Addendum to Agenda Item 6 of the Meeting of the River Hamble Harbour Management Committee on Friday 22 March 2024

- 7.45 27 Feb. Pump out of inundated craft at Warsash. Targeted moorings check on behalf of Moorings Officer.
- 7.46 28 Feb. Marina liaison. Routine patrol craft maintenance. Light traffic.
- 7.47 29 Feb. Recovered a large log from the Main Channel in the Upper River.
- 7.48 01 Mar. Check of a mid-stream moored yacht on behalf of her owner. Pumped out cockpit. Liaison with owner. Commercial tow of a yacht. Re-secured a loose halyard and block on a mid-stream moored yacht. Recovered No 11 light from the Shore adjacent to the Pink Ferry hut. Light showed signs of collision. CCTV investigation proved that light had been working throughout the night until around 0400 in foul weather when an inbound vessel (unidentifiable) had struck the mark off Warsash College Jetty. Light base repaired and light refitted.
- 7.49 02 Mar. Preparations for Trinity House Light Audit (4 March). Pumped out inundated yacht at owner's request.
- 7.50 03 Mar. Recovered a large branch from the Main Channel off Bursledon.
- 7.51 04 Mar. Pump-out of inundated tenders at Warsash. Survey of RHCP Jetty. Liaison with Hampshire Marine Police Unit regarding persons of interest. Annual Trinity House Light Inspection.
- 7.52 05 Mar. Liaison with Hampshire Marine Police Unit. Light traffic in heavy rain.
- 7.53 06 Mar. Attended RHCP Jetty following a report of a missing deck board. Replaced.
- 7.54 07 Mar. Liaison visit from HCC Wildlife Crime Police Officer. Liaison with Hampshire Marine Police Unit regarding persons of interest. Commercial fitting of new pile lines.
- 7.55 08 Mar. Liaison with a mooring holder and the Crown Estate Mooring contractor regarding pontoon chain failure.
- 7.56 09 Mar. Recovery of failed swinging mooring buoy to Warsash. Boat coding work.
- 7.57 10 Mar. Cleaning of small craft safety signage at Swanwick. Berthing assistance given to a motor vessel in difficulty. Replacement of tidal gauge at Crableck. Routine liaison with Hamble Lifeboat.
- 7.58 11 Mar. Recovered a large branch from the Main Channel in the Upper River. Pumped out inundated tenders at Hamble Jetty. Pile Survey at exceptional Low Water (0.3m above Chart Datum).

- 7.59 12 Mar. Continuation of LW pile survey (0.3m above CD). Tide auge maintenance
- 7.60 13 Mar. Mooring inspection on behalf of mooring holder. Commercial making up of mooring lines.
- 7.61 14 Mar. First Aid equipment checks. Maintenance of Aids to Navigation.
- 7.62 15 Mar. Commercial fitting of new pile lines. Stood by a motor vessel aground on Hook Spit (rising tide, lee shore). Successfully refloated.
- 7.63 16 Mar. Assisted a mid-stream mooring holder in replacement of pile lines. Attended Hamble Quay following a report of diesel on the surface. No source apparent. Broken up with jet wash. Assistance given to new mooring holder in picking up his mooring.
- 7.64 17 Mar. Placing of reservation boards on Hamble Jetty. Yard clearance work at Warsash.
- 7.65 18 Mar. Commercial towing in preparation for the Crown Estate's routine pile replacement programme. Liaison with affected owners. Tide gauge cleaning.
- 7.66 19 Mar. Further liaison with mooring holders affected by the Crown Estate pile replacement programme. Preparations for the visit of a tall ship.